



▣ 악취방지덮개 사진(중량물재생센터)



1, 2처리장 일차침전지

<p>현장 사진</p>		
규격	7550(W) × 80340(L) × 1000(H)	
재질	SMC + Al Frame (프레임 일부 백화현황 발생, 설치년도 2007)	

1,2처리장 일차침전지(일부)

<p>현장 사진</p>		
규격	3300(W) × 7000(L) × 1000(H)	
재질	FRP(프레임 없음, 설치년도 2007)	

3처리장 일차침전지

<p>현장 사진</p>		
규격	2000(W) × 50000(L) × 400(H)	
재질	FRP(프레임 없음, 설치년도 2006)	

4처리장 일차침전지

현장 사진



규 격 3300(W) × 4400(L) × 400(H)

재 질 FRP(프레임 없음, 설치년도 2006)

1,2처리장 생물반응조

현장 사진



규 격 2500(W) × 7300(L) × 200(H)


재 질 AL(프레임 + 덮개 등 전체 AL사용)(전반적으로 상태 양호, 설치년도 2007)

▣ 악취방지덮개 사진(서남물재생센터)

1처리장 일차침전지

<p>현장 사진</p>		
<p>규격</p>	<p>5000(W) × 4600(L) × 3000(H)</p>	
<p>재질</p>	<p>PVDF(프레임없음, 설치년도 1999)</p>	

2처리장 일차침전지

<p>현장 사진</p>		
<p>규격</p>	<p>2200(W) × 4200(L) × 700(H)</p>	
<p>재질</p>	<p>FRP(프레임 없음, 설치년도 1999)</p>	


1처리장 생물반응조

<p>현장 사진</p>		
<p>규격</p>	<p>5100(W) × 38000(L) × 600(H)</p>	
<p>재질</p>	<p>PVDF + SS Frame(철재 사용)(프레임 녹, 부식 등 발생, 설치년도 2006)</p>	

2처리장 생물반응조

<p>현장 사진</p>		
<p>규격</p>	<p>2700(W) × 5000(L) × 450(H)</p>	
<p>재질</p>	<p>AL (테두리 철재 사용부분 부식, 녹 등 발생, 설치년도 2006)</p>	

2처리장 반류수처리시설


<p>현장 사진</p>		
<p>규격</p>	<p>3500(W) × 22000(L) × 1200(H)</p>	
<p>재질</p>	<p>FRP (프레임 없음, 설치년도 2011)</p>	

가압부상조(기타시설) - AI Frame 내부 사진


<p>현장 사진</p>		
<p>규격</p>		
<p>재질</p>	<p>SMC + AI Frame (프레임 일부 백화현황 발생하였으나, 상태 양호)</p>	

▣ 악취방지덮개 사진(탄천물재생센터)


1처리장 일차침전지

<p>현장 사진</p>		
<p>규격</p>	<p>1500(W) × 2500(L) × 600(H)</p>	
<p>재질</p>	<p>FRP(프레임 없음, 설치년도 1987)</p>	

2처리장 일차침전지, 생물반응조

<p>현장 사진</p>		
<p>규격</p>	<p>1200(W) × 4000(L) × 600(H)</p>	
<p>재질</p>	<p>FRP(프레임 없음, 설치년도 1995, 1998)</p>	

1처리장 생물반응조

<p>현장 사진</p>		
<p>규격</p>	<p>1500(W) × 5000(L) × 300(H)</p>	
<p>재질</p>	<p>FRP(프레임 없음, 설치년도 1987)</p>	

1처리장 반류수 처리시설

현장 사진




규 격 2400(W) × 1700(L) × 600(H)

재 질 FRP(프레임 없음, 설치년도 1995, 1998)

▣ 악취방지덮개 사진(난지물재생센터)

1처리장 일차침전지

<p>현장 사진</p>	
<p>규격</p>	<p>11500(W) × 11500(L) × 2500(H)</p>
<p>재질</p>	<p>PVDF막(프레임 없음, 설치년도 2002)</p>

무산소조

<p>현장 사진</p>	
<p>규격</p>	<p>2400(W) × 1700(L) × 800(H)</p>
<p>재질</p>	<p>SMC + Al Frame (프레임 일부 백화현상 발생, 설치년도 2012)</p>

악취방지덮개 설치대상지역(생물반응조)

<p>현장 사진</p>	
<p>규격</p>	<p>5100(W) × 38800(L) × 72세트, 5100(W) × 39000(L) × 48세트</p>
<p>재질</p>	<p>SMC + Al Frame</p>