







적출(지적)내용 사진 현황

연번	위 치(적출내용)	관련사진	
1	• 홍제천로2길 54-2 - 맨홀 주변 파손		
2	• 홍제천로2길 54-4 - 도로파손 및 빗물 받이 막힘		
4	• 독립문로3길 3-22 - 보도 및 빗물받이 파손		
5	• 영천동 69-42 - 재난위험시설물 이 상없음		