

서울대공원 지하구내 관로 점검 보고서



서울대공원



(주) 동우기술단

제 출 문

서울대공원 원장 귀하

귀 청와 계약 체결하여 수행한 “서울대공원 지하구내 관로 점검 용역”의 과업을 성실히 수행하고 그 결과와 부속자료를 본 보고서에 수록하여 제출합니다.




2014년 4월

(주) 동 우 기 술 단
대표이사 고 중 호 (인)

참 여 기 술 자

용역기간 : 2014. 02. 26 ~ 2014. 04. 16

성 명	주민번호 (앞6자리)	직 책	기술등급	참여일수	참여내용	확인
김병일	720405- **	부장	고급	2014.02.26.~2014.04.16	사용성검토	
김종덕	671023- **	이사	특급(기술사)	2014.02.26.~2014.04.16	안전성검토	
김균태	700611- **	부장	고급	2014.02.26.~2014.04.16	안전성검토	
김기순	771222- **	과장	초급	2014.02.26.~2014.04.16	현장조사	
마권동	840103- **	대리	초급	2014.02.26.~2014.04.16	현장조사	
김상현	840805- **	대리	초급	2014.02.26.~2014.04.16	보수보강 방안	
남기원	520515- **	기술자문	특급	2014.02.26.~2014.04.16	사용성검토	



시설물 위치도 및 전경

