


우기대비 시설물 안전점검 결과

연 번	점검 일자	시역 사항	점검자	조치결과			비고	
				정비 일자	조치내역	정비사진		
						전		후
1	2019. 6. .	○지하구 잡용수배관 - 배관이탈 보수	백강석 외2	2019. 6. .	배관이탈 보수 작업완료	 	기계	
2	2019. 6. .	○남미관 내실 -바닥배수구 정비	백강석 외2	2019. 6. .	바닥배수구 정비 작업완료	 	기계	
3	2019. 6. .	○동관소 기계실 -배수펌프 정비	백강석 외2	2019. 6. .	배수펌프 정비 작업완료	 	기계	
4	2019. 6. .	○아행관 외부방사장 -배수구정비	백강석 외2	2019. 6. .	배수구정비 작업완료	 	기계	
5	2019. 6. .	○한미음 쉼터 - 순환펌프 정비	백강석 외2	2019. 6. .	순환펌프정비 작업완료	 	기계	

연 번	점검 일자	지적 사항	점검자	조치결과			비고	
				정비 일자	조치내역	정비사진		
						전		후
6	2019. 6. .	○기린사 -기린사 불용전선	정성윤 외2	2019. 6. .	전선철거 작업 완료			전기
7	2019. 6. .	○관리사무소 -투광등 부점등	정성윤 외2	2019. 6. .	투광등 교체 작업 완료			전기
8	2019. 6. .	○남미관 주변 -가로등 안정기 커버 파손	정성윤 외2	2019. 6. .	안정기 커버교체 작업 완료			전기
9	2019. 6. .	○1초소 앞 - 연결살수 설비 송수구 덮개손실	정성윤 외2	2019. 6. .	송수구 덮개교체 작업 완료			전기
10	2019. 6. .	○유인원관 -유도등 부점등	정성윤 외2	2019. 6. .	유도등 교체 작업 완료			전기

연 번	점검 일자	지적 사항	점검자	조치결과			비고	
				정비 일자	조치내역	정비사진		
						전		후
11	2019. 6.10.	산림욕장 등산로 정비	최수영 최종태	2019. 6.25.	노후 계단철거 및 목계단 교체작업완료	 	녹지	
12	2019. 6.10.	산림 내 배수로정비	장숙희 최종태	2019. 6.14.	배수로 내 토사 및 낙엽 정비완료	 	녹지	
13	2019. 6.17.	위험수목 제거	장숙희 최종태	2019 6.17.	위험수목 제거완료	 	녹지	