

위치도 및 현황사진

○ 주소 : 강동구 상일동 상일동역 교차로



○ 현황사진

단차 발생 현장 점검	누수복구 및 단차 위치 비교
<p>A photograph showing the accident site on the road. A white marker is placed on the asphalt to indicate the location of the accident.</p>	<p>A photograph comparing the accident location (blue dashed box) and the repair location (red dashed box) at the intersection. The repair location is further up the road from the accident site.</p>