

현황사진

공사명 : 정원박람회부지 기반조성공사

구분	여의도 공원내	내 용	표토제거
전			
후			

현황사진

공사명 : 정원박람회부지 기반조성공사

구분	여의도 공원내	내 용	절성토
			
			


현황사진

공사명 : 정원박람회부지 기반조성공사

구분	여의도 공원내	내 용	스프링클러 정비
전			
후			

현황사진

공사명 : 정원박람회부지 기반조성공사

구분	여의도 공원내	내 용	수목이식
전			
후			



현황사진

공사명 : 정원박람회부지 기반조성공사

구분	여의도 공원내	내 용	초화류이식
전			
후			



현황사진

공사명 : 정원박람회부지 기반조성공사

구분	여의도 공원내	내 용	수목정비
전	 A photograph showing a park area before construction. A tall, ornate lamp post stands on a paved path. The area is surrounded by various trees, including tall pines and deciduous trees. In the background, a building and some construction equipment are visible.		
후	 A photograph showing the same park area after construction. A white wooden fence has been installed around the lamp post and the surrounding area. The trees and the building in the background are still visible, but the ground around the lamp post is now covered with grass and some small plants.		

현황사진

공사명 : 정원박람회부지 기반조성공사

구분	여의도 공원내	내 용	수목정비
전	 A photograph showing a row of trees in a park area. The trees have dense green foliage. In the background, a modern building with a glass facade is visible. The ground in the foreground is a mix of grass and a paved path.		
후	 A photograph showing the same row of trees in the park area after maintenance. The trees appear slightly more sparse and some leaves are beginning to turn yellow or brown, indicating the start of autumn. The background building and foreground are the same as in the 'Before' photo.		

현황사진

공사명 : 정원박람회부지 기반조성공사

구분	여의도 공원내	내 용	잔디식재
전	 <p>The photograph shows a paved path in a park. On the right side of the path, there is a construction area with stacks of materials, bags, and workers. A worker in a green shirt and black pants is visible in the foreground, looking towards the construction site. A blue signpost is on the left side of the path.</p>		
후	 <p>The photograph shows the same paved path in the park, now clean and finished. The construction materials and workers are no longer visible. The path is surrounded by trees and grass. A blue signpost is on the left side of the path.</p>		

현황사진

공사명 : 정원박람회부지 기반조성공사

구분	여의도 공원내	내 용	잔디식재
전			
후			

현황사진

공사명 : 정원박람회부지 기반조성공사

구분	여의도 공원내	내 용	느티나무식재
전			
후			

현황사진

공사명 : 정원박람회부지 기반조성공사

구분	여의도 공원내	내 용	식생매트
전			
후			