

# 지하안전관리 대비 상수관로 점검결과

〈 강남수도사업소 〉

## 점검대상

- 상수관로 : 서초구 관내 상수관로 93.2km (500mm 이상)

구 경 (mm)	연 장 (m)	구 경 (mm)	연 장 (m)	구 경 (mm)	연 장 (m)
500mm	24,536	1000mm	148	1650mm	1,586
600mm	13,191	1100mm	60	1800mm	5,958
700mm	10,232	1200mm	6,282	2200mm	6,998
800mm	3,932	1350mm	1,237	2400mm	3,595
900mm	10,399	1500mm	5,095		

## 점검개요

- 점검기간 : 2018. 10. 15. ~ 10. 24.(10일간)
- 점 검 자 : 3명(반장 : 박철호, 반원 : 김홍식, 윤달선)
- 주요점검사항
  - 상수관로 상부 지표에 대하여 침하유무를 육안으로 관찰
  - 상수관로 매설 깊이의 1/2에 해당하는 범위의 지표를 대상으로 하고, 상수도 관경 폭 이상을 점검

## 점검결과

- 이상징후 발견없음

## 향후 계획

- 서초구 관내 상수관로에 대하여 상시 순찰 및 점검 시행

붙임 : 지하안전관리 대비 점검사진

[붙임]

## 지하안전관리 대비 점검사진

〈 강남수도사업소 〉



서운로(한전아트센터 옆)



방배중앙로(방배동919-9)



동광로(몽마르뜨공원)



바우미로(양재동4-19)



태봉로(우면동714)



청계산로(청계산입구역)



서초대로(진흥아파트교차로)



사평대로(사평빛물펌프장)



잠원로(뉴코아백화점)



나루터로(잠원동88)



방배로(이수고가 옆)



명달로(서초동1748-65 서초고옆)



반포대로(서초역)



남부순환로(양재역)



강남대로(양재역)



양재대로(염곡동305삼성여객)



방배천로(방배동686-51)



효령로(서울고교교차로)



현릉로(염곡동 200-4)



논현로(양재전화국사거리)