

사 진 대 지

공 사 명 : 낙산공원 산책로 주변 수목식재공사

위 치	낙산공원 산책로 주변	내 용	앵두나무
시 공 전	 <p>A photograph showing the construction site before the work. The area is a rocky slope with sparse vegetation, including some trees with autumn-colored leaves and low-lying shrubs. The ground is uneven and appears to be a natural, somewhat overgrown area.</p>		
시 공 후	 <p>A photograph showing the construction site after the work. The area is now more densely planted with various shrubs and trees, including the specified '앵두나무' (Red-bud tree). The ground is more organized and landscaped, with a clear path or area defined by the new plantings.</p>		

사 진 대 지

공 사 명 : 낙산공원 산책로 주변 수목식재공사

위 치	낙산공원 산책로 주변	내 용	덜꿩나무
<p>시 공 후</p>			
<p>시 공 후</p>			

사 진 대 지

공 사 명 : 낙산공원 산책로 주변 수목식재공사

위 치	낙산공원 산책로 주변	내 용	화살나무
시 공 전			
시 공 후			

사 진 대 지

공 사 명 : 낙산공원 산책로 주변 수목식재공사

위 치	낙산공원 산책로 주변	내 용	황매화
시 공 전			
시 공 후			