

공중선 정비 합동점검 결과 보고(중구)

□ 점검개요

- 점 검 자 : 하대승(중앙전파관리소), 심선아(서울시), 권명주(자치구)
- 점 검 일 : 2018. 5. 24.(목) 13:30 ~ 18:00
- 점검장소 : 중구 충무로 일대 외 2곳(2017년 정비구역)



충무로 18 ~ 퇴계로41길 13 퇴계로63길 8 ~ 퇴계로 337-6 을지로 280-2 ~ 퇴계로 343

○ 세부점검대상

- 참여사업자 : 한전, SKB(대표), LGU+, KT, SKT, 딜라이브, 티브로드

구역명	정비연도	전 주(본)			정비거리(m)
		계	한전주	통신주	
중 구 - 1	2017	19	16	3	515m

□ 점검결과


(단위 : 건)

지적사항	통신사							현장조치
	계	한국전력	K T	SKB	LGU+	기 타		
계	7	1	2	0	1	2	1	
인 입 선	3	1	1	-	-	1	-	
폐선/사선	1	-	-	-	-	-	1	
기 타	3	-	1	-	1	1	-	

※ 기타 : SKT, 딜라이브, 티브로드

작성 자 보도환경개선과장: 권완택 ☎2133-8100 보도안전팀장: 최승호 ☎8142 담당: 심선아 ☎8107

한국전력공사

			
인 입	충무로 18		

KT

				
기 타 (몽친선)	충무로2길 21-2	인 입	퇴계로63길 6-1	

LGU+

			
기 타 (여유장)	충무로2길 10 맞은편		

기타

				
기 타 (늘어진선)	충무로2길 27-1	인 입	충무로2길 29	

현장조치

		
사 선	퇴계로 343-2	

공중선 정비 합동점검 결과 보고(용산구)

□ 점검개요

- 점 검 자 : 하대승(중앙전파관리소), 심선아(서울시), 박종욱(자치구)
- 점 검 일 : 2018. 5. 25.(금) 10:00 ~ 18:00
- 점검장소 : 용산구 한강대로38가길 일대 외 4곳(2017년 정비구역)



한강대로38가길 7-26 ~ 한강대로40길 53



한강대로21길 17-2 ~ 한강대로7길 20



새창로45길 1 ~ 79



원효로56길 3 ~ 28

○ 세부점검대상

- 참여사업자 : 한전, KT(대표), LGU+, SKB, SKT, 세종텔레콤, 딜라이브

구역명	정비연도	전 주(본)			정비거리(m)
		계	한전주	통신주	
용산구-1	2017	37	19	18	600
용산구-3	2017	51	29	22	709

작성 자 보도환경개선과장: 권완택 ☎2133-8100 보도안전팀장: 최승호 ☎8142 담당: 심선아 ☎8107

점검결과

(단위 : 건)

통신사 지적사항	계	한국전력	K T	SKB	LGU+	기 타	현장조치
계	56	0	1	3	20	13	20
인 입 선	22	-	-	2	14	3	3
폐선/사선	33	-	1	1	5	9	17
기 타	1	-	-	-	1	-	-

※ 기타 : SKT, 세종텔레콤, 딜라이브

KT

		
사 선	새창로45길 57	

SKB

					
사 선	한강대로44길 15	인 입	새창로45길 12	인 입	새창로45길 62-2

LGU+





					
인 입	한강대로40길 49	인 입	한강대로44길 15	인 입	한강대로44길 15

	인 입	원효로56길 16		인 입	원효로56길 16		인 입	원효로56길 17
	인 입	원효로56길 20		인 입	원효로56길 26		인 입	원효로56길 26
	사 선	새창로45길 14		인 입	새창로45길 12		기타(늘어진 선)	새창로 153-11
	사 선	새창로45길 21		사 선	새창로45길 23		사 선	새창로45길 25
	인 입	새창로45길 32		인 입	새창로45길 37		인 입	새창로45길 62-2

		
인 입	새창로45길 64	사 선 새창로45길 67-1

기타

		
인 입	한강대로38가길 7-18 맞은편	인 입 한강대로40길 43
		
사 선	원효로56길 20	사 선 원효로56길 21
		
인 입	새창로45길 50	사 선 새창로45길 5
		
사 선	새창로45길 2	사 선 새창로45길 1
		
사 선	새창로45길 5	

	사 선	새창로45길 25		사 선	새창로45길 25		사 선	새창로45길 25
	인 입	새창로45길 50						

현장조치

	사 선	한강대로40길 43		사 선	한강대로44길 20		사 선	한강대로7길 20
	사 선	한강대로7길 18-10		인 입	한강대로7길 18-5		사 선	한강대로7길 18-15
	사 선	한강대로7길 18-15		사 선	한강대로15길 19-19		사 선	한강대로15길 19-28

		
사 선 한강대로 19-16 맞은편	사 선 한강대로 19-16	인 입 한강대로21길 17-15
		
사 선 원효로56길 18	사 선 새창로45길 12	사 선 새창로 153-11
		
사 선 새창로45길 13	인 입 새창로45길 19	사 선 새창로45길 21
		
사 선 새창로45길 41	사 선 새창로45길 59	

공중선 정비 합동점검 결과 보고(강북구)

□ 점검개요

- 점 검 자 : 하대승(중앙전파관리소), 심선아(서울시), 여운상(자치구)
- 점 검 일 : 2018. 5. 29.(월) 10:00 ~ 18:00
- 점검장소 : 삼양로124길 일대 외 2곳(2017년 정비구역)



삼양로 124길 일대



삼양로116길 일대



삼양로 112길 일대

○ 세부점검대상

- 참여사업자 : 한전, SKB(대표), LGU+, KT, SKT, 세종텔레콤, 드림라인, 티브로드

구역명	정비연도	전 주(본)			정비거리(m)
		계	한전주	통신주	
강북구-3	2017	22	12	10	654
강북구-4	2017	16	9	7	740
강북구-5	2017	22	12	10	459

□ 점검결과

(단위 : 건)

지적사항	통신사							현장조치
	계	한국전력	K T	SKB	LGU+	기 타		
계	7	0	0	0	0	0	7	
인 입 선	6	-	-	-	-	-	6	
폐선/사선	1	-	-	-	-	-	1	
기 타	0	-	-	-	-	-	-	

※ 기타 : SKT, 세종텔레콤, 드림라인, 티브로드

작성 자 : 보도환경개선과장: 권원택 ☎2133-8100 보도안전팀장: 최승호 ☎8142 담당: 심선아 ☎8107

□ 현장조치

					
인 입	삼양로124길 15	인 입	삼양로124길 15	인 입	삼양로118길 7-23
					
인 입	삼양로118길 7	인 입	삼양로118길 10-9 맞은편	인 입	삼양로112길 9-7 현대 베스트빌
					
사 선	삼양로112길 9-6				


공중선 정비 합동점검 결과 보고(은평구)

□ 점검개요

- 점 검 자 : 하대승(중앙전파관리소), 이주영(자치구)
- 점 검 일 : 2018. 5. 30.(수) 10:00 ~ 18:00
- 점검장소 : 응암로34길 일대 외 1곳(2017년 정비구역)



응암로34길17 ~ 은평로10길 32



은평로10길 19 ~ 은평로12길 26

○ 세부점검대상

- 참여사업자 : 한전, LGU+(대표), KT, SKB, CJ헬로비전

구역명	정비연도	전 주(본)			정비거리(m)
		계	한전주	통신주	
은평구-2	2017	59	25	34	1,532

□ 점검결과

(단위 : 건)

지적사항 \ 통신사	계	한국전력	K T	SKB	LGU+	기 타	현장조치
계	41	1	1	0	24	3	12
인 입 선	16	-	1	-	10	2	3
폐선/사선	21	1	-	-	11	1	8
기 타	4	-	-	-	3	-	1

※ 기타 : CJ헬로비전

작성 자 | 보도환경개선과장: 권완택 ☎2133-8100 | 보도안전팀장: 최승호 ☎8142 | 담당: 심선아 ☎8107

한국전력공사

		
사 선	응암로34길 29	

KT

		
인 입	은평로10길 17-29	

LGU+

					
사 선	응암로34길 29	인 입	응암로34길 29	인 입	응암로34길 29-4
					
사 선	응암로34길 25	기타 (이중조가)	응암로34길 24	사 선	응암로34길 23-5 맞은편

			기타 (늘어진선)	응암로34길 23-16	사 선	응암로34길 23-18	인 입	응암로34길 23-18
			기타 (늘어진선)	응암로34길 23-16	사 선	응암로34길 23-18	인 입	응암로34길 23-18
			사 선	은평로10길 32-9	인 입	은평로10길 32-9 옆	인 입	은평로10길 32-9 옆
			사 선	은평로10길 32-7	사 선	백련산로 143-1	인 입	백련산로 145
			인 입	응암로34나길 8	사 선	은평로10길 17-5	인 입	은평로12길 18-7

	인 입	은평로10길 22		사 선	은평로10길 26		사 선	응암로34길 21-16
---	-----	-----------	--	-----	-----------	---	-----	--------------

기타

	사 선	은평로10길 27-4 맞은편		인 입	응암로34나길 5		인 입	응암로34길 21-6
--	-----	--------------------	---	-----	-----------	--	-----	-------------

현장조치

	사 선	응암로34길 25		사 선	응암로34길 23-9		기타 (늘어진선)	응암로34길 23-18
	사 선	은평로10길 32-9		인 입	은평로10길 32 맞은편		사 선	응암동100-8

		
인 입 응암로34나길 4	인 입 응암로34나길 4	사 선 응암로34나길 10
		
사 선 은평로12길 18-7	사 선 은평로10길 17-17	사 선 은평로10길 22