

발산119안전센터 차고문 수리 사진

- 수리일자 : 2017. 8. 8.(화)
- 수리업체 : 블루코스텍(주)
- 수리내용 : 차고문 견인 와이어 및 롤러 교체

