

준 공사 진

○ 봉황배드민턴장 바닥정비

구 분	사 진
공사전	 A wide-angle photograph of an outdoor badminton court. The court surface is a mix of sand and dirt, with white lines for the court boundaries. A net is stretched across the court. The background shows a line of bare trees under a clear blue sky, indicating a cold season. The lighting is bright, casting long shadows on the court.
공사후	 A wide-angle photograph of the same badminton court after renovation. The court surface is now a smooth, reddish-brown color, likely a new type of flooring or a well-maintained surface. The white court lines are clearly visible. The background shows lush green trees, indicating a warmer season. The lighting is softer, and there are some plants in the foreground on the right side.

준 공사 전

○ 달마사앞 화장실 계단정비, 수목식재

구 분	사 진
공사전	 A photograph showing a set of concrete steps on a dirt slope. The steps are made of grey concrete and are surrounded by large, light-colored rocks. The ground is a mix of dirt and sparse vegetation. A brick-paved area is visible at the bottom left of the steps.
공사후	 A photograph showing the same set of concrete steps after construction. A black metal railing with a handrail is installed along the side of the steps. The surrounding area is landscaped with green bushes and plants. In the background, a parking lot with several cars and a traditional Korean building are visible.

준 공사 전

○ 비계배드민턴장 주변 산책로 계단, 핸드레일, 야자매트, 수목식재 등

구 분	사 진
공사전	 <p>A photograph showing a dirt path with wooden steps leading uphill in a wooded area. To the left of the path is a concrete drainage ditch with a metal grate. The ground is uneven and covered with dry leaves and some green plants.</p>
공사후	 <p>A photograph showing the same path after construction. The dirt has been replaced with reddish-brown mats. A metal handrail has been installed along the right side of the path. The drainage ditch remains on the left. The surrounding trees and vegetation are visible.</p>

준 공사 전

○ 비계배드민턴장 주변 산책로 계단, 핸드레일, 야자매트, 수목식재 등

구 분	사 진
공사전	 A photograph showing a set of stone steps leading up a hillside in a wooded area. The steps are made of large, flat stones and are surrounded by dirt and fallen leaves. A metal handrail is visible on the right side of the path. A white banner is hanging from a tree in the background.
공사후	 A photograph showing the same area after construction. The stone steps are now partially covered with a layer of reddish-brown soil. A metal handrail is visible on the right side of the path. A white banner is hanging from a tree in the background.

준 공사 진

○ 비계배드민턴장 주변 산책로 계단, 야자매트 설치

구 분	사 진
공사전	 A photograph showing a dirt path with several stone steps leading uphill through a wooded area. The path is surrounded by large trees and fallen leaves. A person is visible in the distance on the path.
공사후	 A photograph showing the same path after construction. The stone steps have been replaced with a continuous mat made of straw or similar natural material, providing a more stable and eco-friendly surface. The surrounding trees and foliage are the same as in the 'Before' image.

준 공사 진

○ 비계배드민턴장 주변 산책로 계단 정비

구 분	사 진
공사전	
공사후	

준 공사 진

○ 비계배드민턴장 주변 산책로 야자매트 설치

구 분	사 진
공사전	 A photograph showing a dirt path in a wooded area before construction. The path is uneven and narrow. In the background, there are two wooden benches and a tree stump in the foreground. The ground is covered with dry leaves and some green plants.
공사후	 A photograph showing the same dirt path after construction. The path is now wider, smoother, and has a reddish-brown color, indicating the installation of a rubber mat. The surrounding environment, including the benches and tree stump, remains the same.